



Recreational Water Inspection Report

Establishment Information	
Facility Name COUNTRY INN & SUITES (WHIRLPOOL)	Facility Type Public Pool (RPP)
Facility ID # HSAT-7QXQC4	Facility Telephone # 262 251-7700
Facility Address W188N11020 MAPLE RD GERMANTOWN, WI 53022	
Licensee Name GERMANTOWN HOSPITALITY GROUP	Licensee Address W188N11020 MAPLE RD GERMANTOWN, WI 53022

Pool Parameters	
Free Available Chlorine/Bromine	32.5
Combined Chlorine	
Oxidation Reduction Potential	
Disinfectant Type	Bromine
Secondary Disinfectant Type	
Secondary Disinfectant Level	
pH	7.8
Alkalinity	
Cyanuric Acid	
Temperature	
Calcium Hardness	
Saturation Index	
Flowmeter Reading(s)	
Pressure Gauges Reading(s)	
Turnover Rate	

Inspection Information		
Inspection Type Complaint	Inspection Date August 14, 2023	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Observed Violations
<p>Total # 1</p> <p>Observed Violations - 14 - Disinfectant / feeders - proper concentration and chemical used. Gas chlorine. This is a Critical violation</p> <p>REPEAT OBSERVATION: The Bromine residual exceeded 20 ppm.</p> <p>Corrective Action(s): The spa must be closed and may not reopen until the Bromine residual comes into an acceptable range. During the inspection, staff closed the spa and started draining the water to fix the problem. Correct By:</p>

17-Aug-2023

Code citation: ATCP 76.14 Disinfectant feeding and residuals. (4) CHEMICAL CONCENTRATIONS AND RESIDUALS. (g) Maximum total bromine. The maximum total bromine in a pool shall not exceed 20 ppm.

Comments:

Complaint on 14-Aug-2023 :📄

Complaint details hyperlinked above for internal access. View the complaint inspections for the hotel and pool for additional details.

After checking the pool room, pool, and pump room, inspector checked the spa. Hotel staff noted that they had located snakes in the spa and removed them from the facility. No snakes were in the spa at the time of inspection. Because snakes were in the spa, inspector checked the pH and disinfectant levels. pH was within range, but the disinfectant level was above the allowed limit.

Spa must be closed until the bromine level drops below 20 ppm.

A follow-up inspection will be conducted on or after August 17th. If the spa is open and the disinfectant level is not within acceptable range, the spa will have to close again, and a reinspection with fees may be assessed by the health dept.

Additionally, the bromine level being above 20 ppm was also observed during the last routine inspection. If this violation is found during the next routine inspection, a reinspection with fees may be assessed by the health dept.

Complaint verified by hotel staff.

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in Washington County Chapter 8.

A re-inspection to assess your correction of these violations will be conducted on, or about, August 17, 2023

Person in Charge

Sanitarian



Jay Duffy



Jacob Levy
(262) 284-8195