



Recreational Water Inspection Report

Establishment Information	
Facility Name COUNTRY INN & SUITES (SWIMMING POOL)	Facility Type Public Pool (RPP)
Facility ID # HSAT-7QWC92	Facility Telephone # 262 251-7700
Facility Address W188N11020 MAPLE RD GERMANTOWN, WI 53022	
Licensee Name GERMANTOWN HOSPITALITY GROUP	Licensee Address W188N11020 MAPLE RD GERMANTOWN, WI 53022

Pool Parameters	
Free Available Chlorine/Bromine	10.5
Combined Chlorine	
Oxidation Reduction Potential	
Disinfectant Type	Bromine
Secondary Disinfectant Type	
Secondary Disinfectant Level	
pH	7.5
Alkalinity	
Cyanuric Acid	
Temperature	
Calcium Hardness	
Saturation Index	
Flowmeter Reading(s)	
Pressure Gauges Reading(s)	
Turnover Rate	

Inspection Information		
Inspection Type Complaint	Inspection Date August 14, 2023	Total Time Spent

OPERATOR - The violations in operating procedure or physical arrangement indicated below must be corrected by the next routine inspection or by a date specified in this report.

Comments:

[Complaint on 14-Aug-2023](#) : 📄

[Complaint details hyperlinked above for internal access. View the complaint inspections for the hotel and spa for additional details.](#)

[When visiting the pool, the hotel pool operator noted that he had found snakes in the pool, pool room, and pump room. The snakes he located were removed from the facility. Inspector did locate a snake shed in the pool room. The staff](#)

member hypothesized that patrons were leaving the exterior fire exit doors open and a pregnant snake was able to access the facility via those doors. The health dept. recommended installing a sign on the doors noting that these doors can not be kept open in order to be in compliance with Wis. Admin. Code ATCP 76 to remind patrons to keep the doors closed. The inspector hypothesized that a pregnant snake was able to access the pump room via an open baffle window that was shielded with a large course mesh grate that could allow a fairly large snake to enter. Further, the mesh present was also broken in areas. Inspector encouraged staff to install a fine mesh grate but is not requiring it at this time. Since snakes were in the pool, disinfectant and pH were checked. Both were within acceptable ranges.

Complaint verified by staff and inspector. No violations written.

Any operator aggrieved by an order of this department under this chapter may request a hearing as provided in Washington County Chapter 8.

Person in Charge



Jay Duffy

Sanitarian



Jacob Levy
(262) 284-8195